



2/11 FIG. 2



3∕11 FIG.3a






FIG.4a




FIG.4c

S1 (0.15, 0.1, 0.2)




FIG.4e

(0.05, 0.05, 0.05)




FIG.4g

(1, 0.05, 0.05) 1 R1 G1 B1

FIG.4b




FIG.4d

S3 S2 (0.266, 0.177, 0.355) (0.563)




FIG.4f

\$3 (0.224, 0.224, 0.224) \$2 (0.224)





FIG.4h

S3 S2 (1, 0.05, 0.05) (1)



5∕11 **FIG**.5a




FIG.5b





FIG.5c



7∕11 FIG.7a




FIG.7b





FIG.7c






FIG.8b




FIG.8c





FIG.8d






FIG.9

10/11 FIG.10





FIG.11



11/11 FIG.12a




FIG.12b

